

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant Brian Clauto		
Inspection Date:	Wednesday, July 22, 2020	Project Contact:			
Spread H: Franklin Roanoke Montgomery	MP247.2-248.4, 240-240.5, 235.2- 235.5 AR-FR 290, 291, 280, MN-279 ATWS 955, 955A, 1225, 1224, 1222, 1223, 725, 727	Weather:	Dry		

Roanoke Montgomery		ATWS 955, 955A, 1225, 12 1222, 1223, 725, 727	224,								
	ACTIVE STAG	SE OF CONSTRUCTION: (Ch	neck all that	apply)							
	Tree Felling	☐ Clearing/Grubbing	☐ Gra	ading	☐ Tren	ching		Strir	nging/Welding		
	Lowering/Backfilling	☐ Final Grading	☐ Ten	np. Stabilization	☐ Pern	n. Stabilization	\boxtimes	Dor	mant		
							Yes	No	N/A		
		trols installed and implemented at control plan and stormwater			roved erosio	n and	\boxtimes				
		ontrol measures properly mair od engineering practices and, v						\boxtimes			
	3. Areas of	offsite sediment deposition of	oserved?					\boxtimes			
	■ Comments: Inspected the following resources: S-G27, S-G26, S-NN16, W-NN8, W-KL 41, W-RR3, W-RR4 ■ ECD's were in place and appeared to be functioning, Routine Maintenance: (72-Hour Deadline from Notification) - St 12442+70 wattle requires repair Ineffective Controls: (24-Hour Deadline from Notification) - N/A Recommended Corrective Action: Maintain and install all controls per the approved PSS&S.										
	<u>Deadline:</u> <u>V</u>	Vithin 72-Hour of Notificati	on_								

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:

Date: Wednesday, July 22, 2020



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, July 22, 2020

 <u>Figure 1</u>: Near St13114 ECDs are in place and permanent style waterbars are in place.



■ Figure 2:Near St12690+00 ECD's are in place and effective.



■ Figure 3. Near St12442+70 ECD wattle requires repair



Figure 4: Near MP 240, ECD's are in place and effective

